


NEW PRODUCT ANNOUNCEMENT



ADAPTER, REPLACEMENT, 4808, SET, U33/U38

Due to the unavailability of the 4808 driver chip used on Tegal® 9XX series etchers, the engineers at Profacture have sourced and designed a replacement.

Compatible replacements are no longer available in the original 18 pin dip style package. The most common today is a 20 pin dip style package.

Adapter PCB's were designed and manufactured to accept these new package styles. Due to the space constraints on the Dacscan it was necessary to design two different types of adapters.


The adapter sets are supplied as a complete assembled set and also come with an 18 pin dip socket for ease of future replacements and Troubleshooting.

This is a far less expensive alternative to purchasing any remaining supplies that Tegal® may have in stock.

For More Information Contact



15690 La Mesa Court
Morgan Hill, CA 95037
United States
408-782-2120
408-778-7466 Fax
www.profacture.com
info@profacture.com



ADAPTER, REPLACEMENT, 4808, SET, U22 - U28

- Product Description:
 - ❖ Tegal® Adapter, Replacement, 4808, Set
- Part Number(s):
 - ❖ PRO-10-3033 for Tegal® Dacscan U33/U38
 - ❖ PRO-10-3034 for Tegal® Dacscan U22 thru U28
- Purpose(s):
 - ❖ Replacement for the unavailable original 18 pin 4808 driver
 - ❖ Low cost alternative to purchasing any remaining originals from Tegal®